



STATE OF VERMONT
 AGENCY OF TRANSPORTATION
 CONSTRUCTION AND MATERIALS
 BUREAU CENTRAL LABORATORY

BORING LOG

Hinesburg HES 021-1(19)
 (GeoDesign #750-09.18)
 Hinesburg, VT

Boring No.: B5-ST
 Page No.: 1 of 1
 Pin No.: 04b204
 Checked By: JFW

Boring Crew: C. Aldrich (Platform), A. Bariboult (GeoDesign)
 Date Started: 5/28/15 Date Finished: 5/29/15
 VTSPG NAD83: N 671701.00 ft E 1479080.00 ft
 Station: 288+81 Offset: 42' LT
 Ground Elevation: 372 ft

Casing Sampler
 Type: FJ TUBE
 I.D.: 4 in 2.87 in
 Hammer Wt: N.A. N.A.
 Hammer Fall: N.A. N.A.
 Hammer/Rod Type: N.A./N.A.
 Rig: Geoprobe 7822DT CE = NA

Groundwater Observations (3)		
Date	Depth (ft)	Notes
05/28/15	12.0	Inferred from B5.

Depth (ft)	Strata(1)	CLASSIFICATION OF MATERIALS (Description)	Blows/ft (N Value)(2)	Moisture Content %	Gravel %	Sand %	Fines %
2.5	x x x	Fill (Inferred from B5)					
5.0	x x x						
7.5	x x x						
10.0		Silty Clay (Inferred from B5)					
10.0		ST-1 (10'-12'): Grey CLAY & SILT, little fine Gravel, trace fine to coarse Sand, moist. (See Remark 5). Rec. = 2.0 ft					
12.5		Hole stopped @ 12.0 ft No refusal.					
15.0							
17.5							

Remarks:
 1. Ground surface elevation, northing, easting, station, and offset shown are approximated from files made from existing features in the field by GeoDesign personnel, the Preliminary Plan Set prepared by VHB and dated 4/30/2015, and an electronic site plan titled "z04b204sv.dgn" provided by VHB via email on June 26, 2015.
 2. B5-ST Located 2' East of B5.
 3. Advanced 4" casing to 10' with pneumatic direct push hammer. Cleaned out casing with a hand auger and bucket (was not cleaned using wash rotary methods).
 4. Backfilled with cuttings and 1.5 bags bentonite chips.
 5. ST-1 soil description based on discussion with GeoTesting Express personnel upon extruding the bottom portion of the tube.

Notes:
 1. Stratification lines represent approximate boundary between material types. Transition may be gradual.
 2. N Values have not been corrected for hammer energy. CE is the hammer energy correction factor.
 3. Water level readings have been made at times and under conditions stated. Fluctuations of groundwater may occur due to other factors than those present at the time measurements were made.

GEODESIGN BORING LOG 750-09.18 HINESBURG.DPJ VERMONT AOT.DOT 7/31/15