


LAMINATE PREPARED FOR REPAIR



COMPLETED REPAIR

LAMINATING A REPAIR ON BUOYANCY FOAM

FIGURE 6.7