



REVISIONS AND CORRECTIONS  
 JULY 17, 1972 HELICAL CORRUGATED COUPLING BAND NOTE ADDED.  
 JULY 24, 1975 GRANULAR MATERIAL AT CULVERT LOCATIONS CORRECTED.  
 OCT 30, 1988 REVISED TO CONFORM WITH 1986 SPECIFICATIONS.

APPROVED: *Dec 6, 1971*  
 R.H. Arnold  
 CHIEF ENGINEER  
 C.H. Stachney  
 ASST CHIEF ENGINEER  
 G.M. Lane  
 HIGHWAY ENGINEER

TYPICAL WATERFALL FOR CULVERTS UP TO AND INCLUDING 48" DIAMETER  
 EXTENSION SERVICE BOX AND CURB STOP  
 CORRUGATED PIPE ELBOW  
 GRANULAR BORROW AT CULVERT LOCATIONS  
 UNDERDRAIN FLUSHING BASIN  
 CORRUGATED STEEL PIPE END SECTION  
 CORRUGATED STEEL PIPE ARCH END SECTION

VERMONT AGENCY OF TRANSPORTATION  
 STANDARD  
 D-4