



**NOTES:**

NOTE "D"  
PROTRUSIONS CAUSED BY WELDING OR GALVANIZING ARE NOT PERMITTED ON THE ADJOINING SURFACES OF THE BOX BEAM RAILS, SPLICE TUBES AND FILL PLATES.

NOTE "E":  
HOLES IN THE POST FOR THE LOWER RAIL MAY BE LOCATED AND DRILLED IN THE FIELD. IF SO, THE GALVANIZING SHALL BE REPAIRED IN ACCORDANCE WITH SECTION 505.

ALL DIMENSIONS ARE SHOWN IN MILLIMETERS UNLESS OTHERWISE NOTED.

PROJECT: <b>EAST MONTPELIER</b>	PROJECT NO. : <b>BRF 028-3(36)</b>
DESIGN FILE NAME: /98b254/str/sb254rd.dgn	PLOT DATE: 03-FEB-2009
IPARM FILE NAME: sb254rd14.1	DRAWN BY: R. PELLETT
DESIGNED BY: VTRANS	CHECKED BY: J. LACROIX
SQUAD LEADER: K. HIGGINS	SHEET: 22 OF 68
BRIDGE RAILING DETAILS SHEET #4	