



NOTES:

BOLTS SHALL BE TORQUED SNUG TIGHT (APPROXIMATELY 100 ft.-lb.).

NOTE *D*: PROTRUSIONS CAUSED BY WELDING OR GALVANIZING ARE NOT PERMITTED ON THE ADJOINING SURFACES OF THE BOX BEAM RAILS, SPLICE TUBES AND FILL PLATES.

RECEIVED
 CK'D BY: JEL OK'D BY: JAG
 FEB 23 2010
 RESUBMIT APPROVED
 BY: KMH DATE: 3/9/10

REV. DATE: DESCRIPTION:	DRAWN BY: ESB	DATE: 2/15/10	CHECKED BY: DCK	SHEET NO. 3 OF 3
	BRIDGE RAILING DETAILS			
STATE OF VERMONT AGENCY OF TRANSPORTATION HIGHWAY TH 43 (BR. 33) OVER WARDSBORO BROOK IN THE TOWN OF JAMAICA IN WINDHAM COUNTY				
1 2/16/10	CONT. NO. BRO 1442 (27)			
	GEN. CONT. RENAUD BROTHERS, INC.			
	ERECTOR: RENAUD BROTHERS, INC.			
	FABRICATOR: PH. (315)736-8312			
	DI HIGHWAY SIGN & STRUCTURE CORPORATION			
	P.O. BOX 123/40 GREENMAN AVE NEW YORK MILLS, N.Y. 13417			
	JOB NO.			R15-03