

Filled out by: **G J Demers**

Date / Time: 07/11/13

### Culvert Inspection Form

Railroad: <b>GMRC</b>	Town: <u>LUDLOW</u>
Valuation Sheet: <b>V 3 / 26</b>	Valuation Stationing: <u>1329 + 76</u>
Mile Post: <b>B 25.18</b>	GPS Coordinates: N: <u>43, 38 617</u> W: <u>72, 66 299</u>

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

2x2'

Height from Rail: 5'

Length: 26' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:

NORTH OUTLET STOPS SHIFTING  
\_\_\_\_\_  
\_\_\_\_\_

EAST SWITCH SMITHVILLE



