

Filled out by: **G J Demers**

Date / Time: 07/15/13

### Culvert Inspection Form

Railroad: <b>GMRC</b>	Town: <u>LUDLOW</u>
Valuation Sheet: <b>V 3 / 26</b>	Valuation Stationing: <u>1361 + 68</u>
Mile Post: <b>B 25.28</b>	GPS Coordinates: N: <u>43.38713</u> W: <u>72.67457</u>

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

2' x 2'

Height from Rail: 4'

Length: 29' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 3

Remedial Action (if any)

NORTH SIDE ROOF COLLAPSING

Additional Notes:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_





