

Filled out by: G J Demers

Date / Time: 08/06/13

### Culvert Inspection Form

Railroad: <b>GMRC</b>	Town: <u>LUDLOW</u>
Valuation Sheet: <b>V 3 / 28</b>	Valuation Stationing: <u>1459+18</u>
Mile Post: <b>B 27.62</b>	GPS Coordinates: N: <u>43.39532</u> W: <u>72.70714</u>

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

24"

Height from Rail: 4'

Length: 21' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any)

NORTH INLET NOT VISIBLE

Additional Notes:



