

Filled out by: G J Demers

Date / Time: 08/08/13

### Culvert Inspection Form

|                                  |  |
|----------------------------------|--|
| Railroad: <b>GMRC</b>            | Town: <u>LUDLOW</u>  |
| Valuation Sheet: <b>V 3 / 30</b> | Valuation Stationing:<br><u>1555 + 59</u>                    |
| Mile Post: <b>B 29.45</b>        | GPS Coordinates:<br>N: <u>43.41899</u><br>W: <u>72.71667</u> |

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

36"

Height from Rail: 4'

Length: 36.5' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any)

Additional Notes:

NORTH OUTLET HEADER BREAKING UP



