

UPDATE

Filled out by: **G J Demers**

Date / Time: 08/08/13

Culvert Inspection Form

| | |
|----------------------------------|--|
| Railroad: GMRC | Town: <u>LUDLOW</u> |
| Valuation Sheet: V 3 / 30 | Valuation Stationing: <u>1559+02</u> |
| Mile Post: B 29.52 | GPS Coordinates: N: <u>43.41945</u> W: <u>72.71783</u> |

Type: Stone box CMP C.I. Concrete ABS Other _____

2x2

Height from Rail: 6'

Length: 30' Height: _____ Width: _____ Depth: _____

Condition Good Fair Poor

Culvert # _____

Number of Photos Taken: 2

Remedial Action (if any)

SOUTH INLET NEEDS CLEANING
NORTH OUTLET TOTALLY COLLAPSED

Additional Notes:





