

Filled out by: G J Demers

Date / Time: 08/23/13

### Culvert Inspection Form

Railroad: <b>GMRC</b>	Town: <u>Mt. Holly</u>
Valuation Sheet: <b>V 3 / 33</b>	Valuation Stationing: <u>1711+77</u>
Mile Post: <b>B 32.41</b>	GPS Coordinates: N: <u>43.43336</u> W: <u>72.75876</u>

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

2.5' x 3.5' w/ WINGWALLS AND CONCRETE APPROX NORTH OUTLET

Height from Rail: 8'

Length: 3A.A' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any)

EAST WINGWALL AT SOUTH INLET WAS COLLAPSED

Additional Notes:

---

---

---



