

UPDATE

Filled out by: **G J Demers**

Date / Time: 09/03/13

Culvert Inspection Form

Railroad: GMRC	Town: <u>Mt. Holly</u>
Valuation Sheet: V 3 / 36	Valuation Stationing: <u>1888 + 62</u>
Mile Post: B 35.75	GPS Coordinates: N: <u>43.45246</u> W: <u>72.80840</u>

Type: Stone box CMP C.I. Concrete ABS Other _____

18" STONE MENDER AT NORTH INLET

Height from Rail: 2'

Length: 20' Height: _____ Width: _____ Depth: _____

Condition Good Fair Poor

Culvert # _____

Number of Photos Taken: 2

Remedial Action (if any)

BOTTOMS OF PIPE COMPLETELY RUSTED OUT THROUGHOUT

Additional Notes:



