

UPDATE

Filled out by: **G J Demers**

Date / Time: 09/04/13

**Culvert Inspection Form**

Railroad: <b>GMRC</b>	Town: <u>Mt. Holly</u>
Valuation Sheet: <b>V 3 / 37</b>	Valuation Stationing: <u>1916 + 26</u>
Mile Post: <b>B 36.29</b>	GPS Coordinates: N: <u>43,44872</u> W: <u>72,81735</u>

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

36"

Height from Rail: 6'

Length: 30' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 3

Remedial Action (if any)

BOTTOM OF PIPE RUSTING OUT

Additional Notes:

2'x2' CAST IRON DI ON NORTH INLET (FROM HIGHWAY CULVERT)





