

UPDATE

Filled out by: **G J Demers**

Date / Time: 09/09/13

**Culvert Inspection Form**

Railroad: <b>GMRC</b>	Town: <u>Mt. Holly</u>
Valuation Sheet: <b>V 3 / 39</b>	Valuation Stationing: <u>2011 + 09</u>
Mile Post: <b>B 38.08</b>	GPS Coordinates: N: <u>43.44717</u> W: <u>72.85229</u>

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

24" CONCRETE HENCK AT SOUTH INLET

Height from Rail: 4'

Length: 43' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any)  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



