

Filled out by: **G J Demers**

Date / Time: 09/11/13

### Culvert Inspection Form

Railroad: <b>GMRC</b>	Town: <u>WALLINGFORD</u>
Valuation Sheet: <b>V 3 / 40</b>	Valuation Stationing: <u>2110 + 96</u>
Mile Post: <b>B 39.96</b>	GPS Coordinates: N: <u>43.45639</u> W: <u>72.87807</u>

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

4'x5' BOX SOUTH INLET HEADER CRACKED

Height from Rail: 15'

Length: 122' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any)

---

---

---

Additional Notes:

---

---

---



