

Filled out by: **G J Demers**

Date / Time: 02/18/13

### Culvert Inspection Form

Railroad: <b>GMRC</b>	Town: <u>SCREWSBURY</u>
Valuation Sheet: <b>V 3 / 43</b>	Valuation Stationing: <u>2249+16</u>
Mile Post: <b>B 42.59</b>	GPS Coordinates: N: <u>43.49180</u> W: <u>72.88048</u>

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

10"

Height from Rail: 1'

Length: 36' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any)

NO INLET COMPLETELY FILLED

Additional Notes:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



