

UPDATE

Filled out by: G J Demers

Date / Time: 09/23/13

### Culvert Inspection Form

Railroad: <b>GMRC</b>	Town: <u>SAREWSBURY</u>
Valuation Sheet: <b>V 3 / 45</b>	Valuation Stationing: <u>2337+63</u>
Mile Post: <b>B 44.26</b>	GPS Coordinates: N: <u>43.50674</u> W: <u>72.90508</u>

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

15"

Height from Rail: 2'

Length: 20' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any)

Aborn Inlet CRUSHED BY MAINTENANCE EQUIPMENT

Additional Notes:

---



---



---



