

Filled out by: G J Demers

Date / Time: 09/26/13

### Culvert Inspection Form

Railroad: <b>GMRC</b>	Town: <u>CLARENDON</u>
Valuation Sheet: <b>V 3 / 47</b>	Valuation Stationing: <u>2464 + 00</u>
Mile Post: <b>B 46.66</b>	GPS Coordinates: N: <u>43,53 222</u> W: <u>72,93 210</u>

Type:  Stone box  CMP  C.I.  Concrete  ABS  Other \_\_\_\_\_

2' x 2'

Height from Rail: 5'

Length: 33' Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition  Good  Fair  Poor

Culvert # \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any)

PLUGGED AT BOTH ENDS

Additional Notes:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



