

Filled Out By: G. DEMERS

Date/Time: 6/3/10

Culvert Inspection Form

Railroad: <u>WACR CRL</u>	Town: <u>BRADFORD</u>
Valuation Sheet: <u>V43</u> <u>27</u>	Valuation Stationing: <u>1416 + 44</u>
Mile Post: <u>D 14.15</u>	GPS Coordinates: N: <u>43 58 30</u> W: <u>72 06 58</u>

Type: Stone Box Culvert CMP C.I. Concrete ABS (Plastic) Other:

Height from Rail: 20' +

Length: _____ Height: 4' Width: 4' Depth: _____

Condition: Good Fair Poor

Culvert #: 149.85

Number of Photos Taken: 2

Remedial Action (if any):

EAST HEADER WALL BREAKING UP ON SOUTH SIDE

Additional Notes:



