

UPDATE

Filled Out By: G. DEMERS

Date/Time: 7/12/10

**Culvert Inspection Form**

Railroad: <u>WACR CRL</u>	Town: <u>FAIRLEE</u>
Valuation Sheet: <u>V43</u> <u>22</u>	Valuation Stationing: <u>1151 + 71</u>
Mile Post: <u>D 19.16</u>	GPS Coordinates: N: <u>43 54 29</u> W: <u>72 08 26</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

DRAIN IS 2x2

Height from Rail:

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 144, 84

Number of Photos Taken: 2

Remedial Action (if any):

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:

NBW 2009  
\_\_\_\_\_  
\_\_\_\_\_



BAHON FOUNDRY INC.

