

Filled Out By: G J Dennis

Date/Time: 07/26/11

### Culvert Inspection Form

Railroad: <u>WACR CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43/88</u>	Valuation Stationing: <u>4603 + 48.5</u>
Mile Post: <u>L 17.01</u>	GPS Coordinates: N: <u>44 42.892</u> W: <u>72 08.490</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

3' X 3'

Height from Rail: 10' +

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 66 G

Number of Photos Taken: 2

Remedial Action (if any):  
CAPSTONE BROKEN ON EAST END (OUTLET)

Additional Notes:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

170



