

Filled Out By: GJ DEMERS

Date/Time: 08/05/11

### Culvert Inspection Form

Railroad: <u>WACR CRL</u>	Town: <u>BARTON</u>
Valuation Sheet: <u>V43/86</u>	Valuation Stationing: <u>4510 + 48</u>
Mile Post: <u>L18.27</u>	GPS Coordinates: N: <u>44 42, 200</u> W: <u>72 06. 628</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

3' x 3'

Height from Rail: 10' +

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 62A

Number of Photos Taken: 2

Remedial Action (if any):

EAST END (OUTLET) STARTING TO BREAK UP

Additional Notes:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_





