

Filled Out By: G. DEMERS

Date/Time: 7/1/10

### Culvert Inspection Form

Railroad: <u>WARR CRL</u>	Town: <u>LYNDON</u>
Valuation Sheet: <u>V43</u> <u>73</u>	Valuation Stationing: <u>3847 + 06.5</u>
Mile Post: <u>L 31.33</u>	GPS Coordinates: N: <u>44 34 50</u> W: <u>71 58 56</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

4' x 3'

Height from Rail: 10'

Length: \_\_\_\_\_ Height: 4' Width: 3' Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 50-B

Number of Photos Taken: 2

Remedial Action (if any):

EAST END (INLET) 2/3 FULL

Additional Notes:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

313



