

UPDATE

Filled Out By: G. DEMERS

Date/Time: 5/18/10

**Culvert Inspection Form**

Railroad: <u>WACR CRL</u>	Town: <u>LYNDON</u>
Valuation Sheet: <u>V 43</u> <u>68</u>	Valuation Stationing: <u>3569 + 77</u>
Mile Post: <u>L 36.58</u>	GPS Coordinates: N: <u>44 30 35</u> W: <u>71 59 39</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

3'

Height from Rail: 3'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 47 A

Number of Photos Taken: 2

Remedial Action (if any):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



163



