

UPDATE

Filled Out By: G. DEMERS  
Date/Time: 5/17/10

Culvert Inspection Form

Railroad: <u>WACR CRL</u>	Town: <u>ST. JOHNSBURY</u>
Valuation Sheet: <u>V 43</u> <u>63</u>	Valuation Stationing: <u>3307 + 12.9</u>
Mile Post: <u>L 41.57</u>	GPS Coordinates: N: <u>44 26 38</u> W: <u>72 01 05</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:  
18"

Height from Rail: 6'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 44 K

Number of Photos Taken: 2

Remedial Action (if any):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
PIPE IS BENDING  
\_\_\_\_\_  
\_\_\_\_\_

RELOCATED HOUSE





