

UPDATE

Filled Out By: G J DEMERS

Date/Time: 10/26/11

**Culvert Inspection Form**

Railroad: <u>WACR CRL</u>	Town: <u>ST. JOHNSBURY</u>
Valuation Sheet: <u>V43/61</u>	Valuation Stationing: <u>3181 + 79.2</u>
Mile Post: <u>L 43.93</u>	GPS Coordinates: N: <u>44 24.661</u> W: <u>72 01.073</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

36" CONCRETE DI IN ROAD ON WEST SIDE

Height from Rail: 6'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 43A

Number of Photos Taken: 2

Remedial Action (if any):  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Additional Notes:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



