

Filled Out By: G. Demers

Date/Time: 06/07/10

### Culvert Inspection Form

|                                   |  |
|-----------------------------------|--|
| Railroad: <u>WACC CRL</u>         | Town: <u>RYEGATE</u>   |
| Valuation Sheet: $\frac{VAB}{46}$ | Valuation Stationing: <u>2430 + 46</u>                       |
| Mile Post: <u>L58.16</u>          | GPS Coordinates:<br>N: <u>44 13 42</u><br>W: <u>72 03 17</u> |

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

3' x 3'

Height from Rail: 50'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 27 G

Number of Photos Taken: \_\_\_\_\_

Remedial Action (if any):

EAST END (OUTLET WAS COLLAPSED)

Additional Notes:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



06/08/2010











