

Filled Out By: G. DEMERS

Date/Time: 06/16/10

### Culvert Inspection Form

Railroad: <u>WACR CRL</u>	Town: <u>RYEGATE</u>
Valuation Sheet: <u>V43</u> <u>43</u>	Valuation Stationing: <u>2855 + 83</u>
Mile Post: <u>L 61.47</u>	GPS Coordinates: N: <u>44 11 00</u> W: <u>72 03 39</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

NOT VISIBLE

Height from Rail: 3'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: 26 Q

Number of Photos Taken: 2

Remedial Action (if any):

WOODEN HANDRAILS COLLAPSED

Additional Notes:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



15



