

UPDATE

Filled Out By: G Demers

Date/Time: 6/10/10

**Culvert Inspection Form**

Railroad: <u>WACR CR1</u>	Town: <u>RYEGATE</u>
Valuation Sheet: <u>V43</u> <u>42</u>	Valuation Stationing: <u>22.10 + 62</u>
Mile Post: <u>L 62.32</u>	GPS Coordinates: N: <u>44 10 18</u> W: <u>72 03 16</u>

Type:  Stone Box Culvert  CMP  C.I.  Concrete  ABS (Plastic)  Other:

24"

Height from Rail: 2'

Length: \_\_\_\_\_ Height: \_\_\_\_\_ Width: \_\_\_\_\_ Depth: \_\_\_\_\_

Condition:  Good  Fair  Poor

Culvert #: \_\_\_\_\_

Number of Photos Taken: 2

Remedial Action (if any):

ERODED ON EAST END (OUTLET)

Additional Notes:



