

CENTERLINE SIDEWALK STRINGER OVER FIRST BRACKET
FROM ABUTMENT 2 HAS CRUSHED AND DROPPED AWAY
FROM SLAB APPROX. 1"

