

CHORD RUSTED THRU



75% OF BOTTOM CHORD RUSTED THROUGH
AT PANEL POINT 4 (OUTSIDE CHANNEL AND
SPlice PLATE RUSTED COMPLETELY THROUGH)