

CORROSION DUE TO LEAKING WEEP TUBE

