

60%-70% SECTION LOSS ALONG BOTTOM FLANGE
OF STRINGER 2 IN FLOORBEAM BAY 4

