

50% OF BEARING #6 IS UNDERMINED DUE TO SEVERE SPALLING ALONG ABOUT. #2 BRIDGE SEAT

