

full height vertical crack at abutment #1

