

























SHEARED CONN. BOLTS AT EAST END OF DIAPHRAGM #2
IN SPAN #2 DUE TO OVERHEIGHT VEHICLE IMPACT

