

A close-up photograph of a dark gray asphalt surface. The surface is heavily textured with small stones and is marked by several prominent, irregular cracks. A horizontal crack runs across the upper third of the image. Two more cracks, one on the left and one on the right, run diagonally from the top towards the bottom. The bottom edge of the image shows a lighter, possibly concrete or repair material, bordering the asphalt.

05.04.2007 09:56