









Small trees at inlet need to be removed.

