

A photograph of a concrete culvert inlet. A large, thick tree branch has fallen across the entrance of the culvert, partially blocking it. The culvert is made of concrete and has a semi-circular opening. The surrounding area is overgrown with trees and bushes, some of which have autumn-colored leaves. The ground in front of the culvert is rocky and covered with fallen leaves and debris. The background shows a steep, vegetated hillside.

Small trees at inlet need to be removed.