




Craddle headwall at outlet should be plumbed and anchored.






Bank erosion should be repaired.







Culvert at inlet end needs to be repaired
and a collar installed.





Culvert at outlet needs to be reset and a collar installed



