





Minor perforations.



Minor perforations





Small beaver dam at inlet end of pipe



Trees and debris needs to be removed from inlet end of pipe.







