

Extensive corrosion and scattered perforations throughout.

