







Outlet end of culvert should be repaired and a collar installed. Outlet has pulled apart and dropped about 1 foot.



















Trees in channel at outlet need to be removed.

