

Trees in channel at outlet need to be removed.

