



Directional road sign


75
40







Heavy corrosion throughout pipe.





Creddie headwall at inlet should be anchored and erosion repaired.











