

Creddie headwall at inlet should be anchored and erosion repaired.

