



















**ABRASION ALONG THE INVERT
REBAR EXPOSED**













