

**ABRASION ALONG THE INVERT
REBAR EXPOSED**

