









Minor corrosion throughout.



Beaver dam at inlet needs to be removed





Beaver dam needs to be removed

