

113



450.  
NEW TANK - BENT. SAG

W

Bank erosion needs to be repaired.

















Wingwall east side of box at inlet needs repair or replacement.









Minor bank repair at outlet.

